En

SEPA POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION VI 13676			
NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.			
A. SITE NAME Giles Brothers Lumber Co.	B. STREET (or other identifier) Highway 105 West, Box 701		
c. city	D STATE OF THE COUNTY NAME		
Montgomery	TX	77356	Montgomery 339
G. OWNER/OPERATOR (II known) 1. NAME 2. TELEPHONE NUMBER			
unknown			
H. TYPE OF OWNERSHIP (if known) 1. FEDERAL 2. STATE 3. COUNTY 4. MUNICIPAL X 5. FRIVATE 6. UNKNOWN			
I. SITE DESCRIPTION			
Creosote wood processing plant			
·			,
TKD 008 433971			
J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)			K. DATE IDENTIFIED (mo., day, & yr.)
Review of Texas Department of Water Resources files 10/25/84			
Potential for soil and ground water contamination from creosote,			
pentachlorophenol (PCP), polynuclear aromatics and trace organics			
such as dioxin.			
SUPERFUND FILE			
FEB 1 2 1993			
			•
REORGANIZED	3012 site		
·			
M. PREPARER INFORMATION 1. MAME A A A A A A A A A A A A A A A A A	2. TE	LEPHONE NUMBER	3. DATE (mo., day, & yr.)
Canil of Merions	512	2-475-6371	10/29/84
S.P.A. Form 2070—8 (5—80)			

90070112